Sanitized Copy Approved for Release 2009/12/23 : CIA-RDP81T00618R000100730001-8

(13)

226

ROUTING			
TO:	NAME AND ADDRESS	DATE	INITIALS
1			
2			
3			
4			

	ACTION		DIRECT REPLY		PREPARE REPLY
	APPROVAL		DISPATCH		RECOMMENDATION
	COMMENT		FILE		RETURN
	CONCURRENCE		INFORMATION		SIGNATURE

REMARKS:

FROM: NAME, ADDRESS, AND PHONE NO.	DATE

SECRET

(Security Classification)

25X1

CONTROL NO. Z-303537/81

NPIC/PEG (06/81)

Warning Notice
Intelligence Sources and Methods Involved
NATIONAL SECURITY INFORMATION
Unauthorized Disclosure Subject to Criminal Sanctions

SECRET

(Security Classification)

Sanitized Copy Approved for Release 2009/12/23 : CIA-RDP81T00618R000100730001-8

25X1
Sanitized Copy Approved for Release 2009/12/23 : CIA-RDP81T00618R000100730001-8

Page Denied

Next 1 Page(s) In Document Denied

Sanitized Copy Approved for Release 2009/12/23 : CIA-RDP81T00618R000100730001-8

Sanitized Copy Approved for Release 2009/12/23 : CIA-RDP81T00618R000100730001-8

SECRET

25X1

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

Page 1 of 1

Attachment to Z-303537/81
NPIC/PEG (6/81)

Copy____

BOMB DAMAGE ASSESSMENT
BAGHDAD NUCLEAR RESEARCH CENTER, IRAQ

25X1

1. (S/D) SIGNIFICANCE: ASSESSMENT OF BOMB DAMAGE TO THE FRENCH REACTOR AREA AT BAGHDAD NUCLEAR RESEARCH CENTER.

2. (S/D) REMARKS: DAMAGE IS OBSERVED AT BAGHDAD NUCLEAR RESEARCH CENTER. THAT THE STRUCTURAL DAMAGE TO THE ISIS REACTOR BUILDING IS LESS SEVERE THAN PREVIOUSLY REPORTED. THE NORTHEAST SECTION OF THE ROOF OF THE ISIS REACTOR HAS SUSTAINED MINOR DAMAGE. PIECES FROM THE ROOF OF THE OSIRAK REACTOR BUILDING ARE LAYING ON TOP OF THE ISIS REACTOR BUILDING. DAMAGE TO THE INTERIOR OF THE ISIS REACTOR BUILDING CANNOT BE DETERMINED. THE OSIRAK REACTOR BUILDING DOES NOT APPEAR TO HAVE SUFFERED A DIRECT BOMB HIT. THE WALLS ARE WARPED OUT OF ROUND AND PART OF THE ROOF HAS FALLEN INSIDE. THIS DAMAGE IS PROBABLY DUE TO AT LEAST FIVE BOMBS WHICH FELL TO THE EAST OF THE OSIRAK REACTOR BUILDING AND WITHIN THE METAL SCREEN. SOME OF THE INTERIOR COMPONENTS OF THE BUILDING ARE VISIBLE. 25X1

(S/D) CLEANUP WORK IS NOT OBSERVED AT ANY OF THE DAMAGED BUILDINGS; HOWEVER, PEOPLE ARE AT A GARAGE (NOT ON GRAPHIC) IN THE CENTRAL SECTION OF THE INSTALLATION. THIS GARAGE IS IMMEDIATELY WEST OF THE DESTROYED AND DAMAGED SUPPORT BUILDINGS.

(S/D) IN ADDITION TO THE FIVE BOMB CRATERS AT THE OSIRAK REACTOR BUILDING, AN UNDETERMINED NUMBER OF CRATERS ARE IN THE AREA OF THE DESTROYED AND DAMAGED SUPPORT BUILDINGS. ALSO, ONE CRATER IS ON THE WEST SIDE OF LABORATORY TWO AND ONE CRATER IS ON THE WEST SIDE OF LABORATORY ONE (NOT ON GRAPHIC).

3. COORDINATES 33-12-26N 044-31-08E 25X1

COMMENTS AND QUERIES REGARDING THIS BRIEFING BOARD MAY BE DIRECTED TO THE NPIC/PEG OPERATIONS OFFICER.

25X1

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

WARNING NOTICE
Intelligence Sources
and Methods Involved

SECRET

25X1

Sanitized Copy Approved for Release 2009/12/23 : CIA-RDP81T00618R000100730001-8